

US EPA ARCHIVE DOCUMENT

UNIT LOG	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 05/02/2012	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/26/12 – 0700, 05/03/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
09:00	<p>Operational status:</p> <ul style="list-style-type: none"> MP10.75, observed crews installing the sediment trap. MP10.75, sheen observed as crew installs the sediment trap. Observed sediment collection devices to be installed at the sediment traps. RI crew observed at MP10.0 LDB. OB9.10, no sheen observed. OB8.97, no sheen observed. MP8.5 island, tar patties observed. 		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			